


# CEMA Safety Labels Placement Guidelines


Product: Bulk Handling Equipment

Equipment: Vertical Screw Conveyors (SC-3)



Use Label "A" on belt guard.



Use Label "B" on ends of trough, on intake inspection door, and both sides of discharge spout.



BOTH SIDES

"B"

"B"

-  NEAR SIDE
-  FAR SIDE



"A"

To be placed on removable guards to warn that operation of the machinery with guards removed would expose chains, belts, gears, shafts, pulleys, couplings, etc. which create hazards.



"B"

To be placed on inlets and discharges, troughs, covers, and inspection doors of screw conveyors to provide warning against exposed moving parts while in operation